

Feature: D20 High Capacity Color

Added ability to use high capacity color cartridges in an Imation D20.  
(Requires Firmware, Driver and SureThing update to latest version)

182: Feature - Capacity data bars

Add different size total capacity data bars for each of the disc types.

184: Feature - Hot Keys

Added hot keys for better navigation. For key combinations open any of the menus.  
Items with hot keys have the key combination in parenthesis.

166: Feature - SureThing Image Launch

Double clicking on the SureThing image will launch SureThing with the selected label.

157: Feature - There is no option for Model and Mode2 XA in a Data job.

Added an option for Mode 2 Data Discs.

194: Feature: PTCalibration Utility

Add Pick Depth Calibration to PTCalibration Utility

168: Bug - Certain Wav files can't be added to Audio Job

Added a warning when audio files that don't have the following specs are added to a job:

Bit Rate: 1411 kbps

Audio Sample Rate: 16bit

Channels: 2 (stereo)

Audio Sample Rate: 44 khz

169: Bug - Drive tray does not open after successful data burn

Fixed issues with drive tray not opening after rejects and other situations if conflicting DLA software is installed.

171: Bug - PTPublisher doesn't run as a User or Power User on XP

Fixed issues running the software with only user privledges - Will now run as user or power user as long as "Everyone" is given Manage Printers, Manage Documents Rights for the Disc Publisher printer.

174: Bug - Adding certain types of files fails (image and audio)

Fixed a bug where files without all lowercase extensions in Audio and Image jobs were not able to be added to a job.

185: Bug - Tech Support Report not saving all log files for PTPublisher

Fixed a bug in the tech support report that prevented the report from getting the latest log files.

189: Bug - Test Burn is actually burning to DVD-R instead of testing.

Fixed with updated 3.6.36.500 burn engine

144: Bug - Media should change to custom when changing print quality.

Media now automatically changes to custom if any print setting is changed on step two of the job wizard.

145: Bug - With no robot connected - get unknown error when clicking copy jobs.

Fixed a bug where the user received an unknown error when clicking copy job with no robot connected.

151: Bug - If user adds too much data to Data Job no warning or message is logged. Added warning if too much data is added to a data job based on the currently set disc type. Error now appears in the log.

152: Bug - Calibration utility does not launch from PTPublisher - DevComponents.DotNetBar.dll because it did not install. Fixed a bug that caused the calibration utility to fail to launch.

154: Better Logging  
Improved logging messages of job and disc info, switched order of completed jobs to show latest jobs first.

161: Bug - Problems opening and closing discs in Audio Job. All discs left open may cause some older players not to play discs. Fixed a bug where audio jobs weren't being closed.

164: Bug - Crash after robot unplugged and clicking Cancel  
Fixed crash after robot unplugged and clicking Cancel

165: Bug - Abort job action not clearing any remaining robotic error. When a job causes a robotic error and is aborted then the robotic error will be cleared.

114: Bug - Prompt for insufficient Resolution on Print step must be dismissed twice. Fixed a bug that caused two of the same warning messages on image (jpg, bmp) files that are either not square or low res.

199: Bug - Options Menu - Applications Paths tab does not save path if custom path is used.  
Fixed bug that caused custom inability to save custom paths.

143: Bug - Low Ink Warning message appears at start of many disc jobs. Added a warning that informs the user that not have enough ink is available to complete the job. Can now ignore or change cartridge.

Bug- Various recording errors during DVD recording jobs.  
Updated burn engine to version 3.6.36.500 to fix DVD recording errors.

3: Calibration Utility

Added a calibration utility that is launched from the Printer Properties page. This is used to set bin positions, center the print image, run last disc calibration, etc.

10: Allow PTP to launch if no robot is found

PTPublisher will now open even if no robot is found. This allows the user to create/modify/save jobs without a robot connected.

11: Job Queuing

Added job queuing feature which allows the user to queue up multiple jobs at a time.

76: Audio Copy job - doesn't "find" disc to copy if the disc has already been inserted

Bug Fix: When performing a copy job of an audio CD the first step would display a "Checking for disc in drive" message indefinitely.

61: Add Kiosk Mode check box in PTPublisher Options

Added a kiosk mode option when the robot supports kiosk mode (Disc Publisher II). The option can be found on the options tab under the Tools - Options menu.

64: Disc Type not saved with job

Bug Fix: Disc type was not always saved with the job.

18: Cannot add .ISO files in PTPublisher

PTPublisher can now burn ISO image files.

37: Launching explorer dialog is slow

Explorer Dialog (Get Files) will now load faster. Also fixed some display and color theme issues.

4: VISTA Fix

PTPublisher now works with Microsoft Windows Vista.

9: Volume name not saved with job

Bug Fix: The volume name was not displayed when opening a saved job.

1: 800x600 Resolution

Bug Fix: When monitor resolution was set to 800x600 certain windows and buttons were not fully accessible.

2: Clean Print Issue

Bug Fix: After doing a Clean Print, the software would not allow any more jobs until restarted.

\*29: Blu-Ray capacity incorrect

Bug Fix: User interface bugs regarding Blu-Ray disc capacity and job types.